

## How to report a bug to Streamline Automation:

Collect all possible information including...

- 1- *Project File (if possible, recreate file, save-as right before issue)*
- 2- *3D Model and/or DXF*
- 3- *Detailed description of the bug and what actions lead to it.*
- 4- *Include **SOFTWARE NAME** and **VERSION NUMBER***

Send to:

[TechServices@FROG3D.com](mailto:TechServices@FROG3D.com)

<b>Version:</b>	<b>12.8.0</b>	<b>Release Date:</b>	<b>2025/07/31</b>
Licensing	Improved License & Server Security.		

<b>Version:</b>	<b>12.2.1</b>	<b>Release Date:</b>	<b>2024/08/15</b>
User Guide	Updated help file from html to pdf.		

<b>Version:</b>	<b>12.2.0</b>	<b>Release Date:</b>	<b>2024/06/13</b>
Save File	Fixed LPJ file does not open when path name is too long.		

<b>Version:</b>	<b>12.1.0</b>	<b>Release Date:</b>	<b>2023/11/16</b>
Licensing	Improved method of identifying pc.		

<b>Version:</b>	<b>12.0.1</b>	<b>Release Date:</b>	<b>2023/09/25</b>
Messages	Updated Licensing Prompt.		

<b>Version:</b>	<b>12.0.0</b>	<b>Release Date:</b>	<b>2023/09/25</b>
Licensing	Now uses online license. USB key license deactivated. V12.0 +		